

Copper Rose by FusionBeads.com



Approximate finished length: 1.5 inches

Beads and other products needed for one pair of earrings:

- 2 - 20x9mm Rose Teardrop Czech Pressed Glass Beads (GL7812)
- 2 - 6mm Antique Copper Plated Pewter Leaf Bead Caps by TierraCast® (CP2111)
- 2 - 10mm Antique Copper Plated Pewter Oak Leaf Bead Caps by TierraCast® (CP2125)
- 2 - 24 gauge Copper 3 inch Head Pins (DA0205)
- 1 pair - 10mm Copper Ear Wires with Front Loop (DA0123)

Tools needed to complete the earrings:

- Round nose pliers
- Chain nose pliers
- Wire cutters

Beading Techniques needed to complete the earrings:

- Wire Wrapping
- Attaching an Ear Wire

*For step-by-step photos and instructions on these and other techniques, visit FusionBeads.com and select *Beading Techniques* from the top navigation bar.*

Instructions to complete “Copper Rose” earrings:

Step 1

Place these beads in the following sequence onto a head pin, making one unit:

1 – 10mm oak leaf bead cap (cupped side away from the head)

1 – rose teardrop bead (large end first)

1 – 6mm leaf bead cap (cupped side toward the previous bead)

Step 2

Wire wrap (see Wire Wrapping Technique) this unit to the loop on one ear wire.

Step 3

Repeat Steps 1 and 2 for the second earring.

For more Inspiration jewelry ideas and to meet all your beading needs, visit FusionBeads.com!