

So Berry Sweet by FusionBeads.com



Approximate finished length:1.5 inches

Beads and other products needed for one pair of earrings:

34 - 4mm Fuchsia Round Czech Pressed Glass Beads (GL1192)

1 pair - 30mm Gold-Filled Beading Hoops (GF2507)

14 - 22 gauge Gold-Filled 1.5 inch Head Pins (GF2766)

Tools needed to complete the earrings:

Round nose pliers

Chain nose pliers

Wire cutters

Beading Techniques needed to complete the earrings:

Simple Loop

For step-by-step photos and instructions on these and other techniques, visit FusionBeads.com and select Beading Techniques from the top navigation bar.

Instructions to complete “So Berry Sweet” earrings:

Step 1

Place one round glass bead onto one head pin, making one unit. Turn a simple loop (see Simple Loop Technique) at the open end of the head pin.

Step 2

Repeat Step 1 six times, making a total of seven units.

Step 3

String the following onto one beading hoop in the following sequence:

1 – round bead

1 – bead unit

Repeat the sequence six times, stringing one more round bead after the last repeat.

Step 4

Using chain nose pliers, grasp the straight tip of the beading hoop, and bend it at a right angle. The loop at the end of the beading hoop will catch the bent end.

Step 5

Repeat Steps 1 – 4 for the second earring.

For more Inspiration jewelry ideas and to meet all your beading needs, visit FusionBeads.com!