

Metallic Moon by FusionBeads.com



Approximate finished length: 7 inches

Beads and other products needed for one bracelet:

13 - 11mm Rhodium Plated Pewter Hammered Round Links by TierraCast® (SP2262)

1 - 22x16.5mm Rhodium Plated Pewter Hammered Teardrop Toggle Clasp by TierraCast® (SP2276)

16 - 5mm 18 gauge Silver Plated Base Metal Jump Rings (BM2832)

Tools needed to complete the earrings:

Chain nose pliers

Beading Techniques needed to complete the bracelet:

Opening and Closing a Jump Ring

For step-by-step photos and instructions on these and other techniques, visit FusionBeads.com and select Beading Techniques from the top navigation bar.

Instructions to complete "Metallic Moon" bracelet:

Step 1

Open one jump ring (see Opening and Closing a Jump Ring Technique). Use the jump ring to attach the ring side of the toggle clasp to one hole in one round link. Close the jump ring.

Step 2

In the same manner as in the previous step, use jump rings to continue connecting 12 more round links together into a continuous chain.

Step 3

Open one jump ring, and attach it to the last round link. Close the jump ring.

Step 4

Open one jump ring, and attach it to the loop on the bar side of the toggle clasp. Close the jump ring.

Step 5

Open one jump ring, and use it to connect the jump ring from Step 3 to the jump ring from Step 4. Close the jump ring.

For more Inspiration jewelry ideas and to meet all your beading needs, visit FusionBeads.com!