

Pretty Belle by FusionBeads.com



Approximate finished length: 1.25 inches

Beads and other products needed for one pair of earrings:

- 2 - 4mm Rose Preciosa Czech Crystal Round Beads (PC0185)
- 2 - 6x4mm Light Milky Pink Baby Bell Flowers Czech Pressed Glass Beads (GL1684)
- 2 - 6x8mm Dark Pink with White Day Lily Czech Pressed Glass Beads (GL2351)
- 2 - 8x12mm Rose Opal Day Lily Czech Pressed Glass Beads (GL7637)
- 2 - 7.5mm Antique Gold Plated Pewter Leaf Bead Caps by TierraCast® (GP2230)
- 1 pair - 10.5mm Gold-Filled Ear Wires with Front Loop (GF2106)
- 2 - 24 gauge Gold-Filled 2 inch Head Pins (GF2759)

Tools needed to complete the earrings:

Round nose pliers
Chain nose pliers
Wire cutters

Beading Techniques needed to complete the earrings:

Wire Wrapping

For step-by-step photos and instructions on these and other techniques, visit FusionBeads.com and select Beading Techniques from the top navigation bar.

Instructions to complete "Pretty Belle" earrings:

Step 1

Place these beads onto one head pin, making one unit:

- 1 – 4mm Rose crystal round bead
- 1 – 6x4mm light milky pink baby bell flowers bead
- 1 – 6x8mm dark pink with white day lily bead
- 1 – bead cap (cupped side toward the previous bead)
- 1 – 8x12mm rose opal day lily bead

Step 2

Wire wrap (see Wire Wrapping Technique) this unit to the loop on one ear wire.

Step 3

Repeat Steps 1 – 2 for the second earring.

For more Inspiration jewelry ideas and to meet all your beading needs, visit FusionBeads.com!